

New fencing

- Existing fence from dugouts to outfield fence will be replaced. In addition, poles that have heaved out of the ground will be fixed/replaced. New gates will be added due to addition of back stop netting project.

New fence topper

- Currently on top of all our black fencing we have a yellow fence topper installed. That extends from dugouts all the way around the outfield to the other dugout. It has faded to a dull yellow and has just aged to a point where it needs replaced.

Outfield windscreen – Batters eye view

- Today we have no windscreen on the outfield fence to help break up the batters' eye view and allow them to pick up the pitched ball. We are looking to add 80' to the center of the outfield to assist with that.

New Bullpens

- Our current bullpens need repair. They are currently made up of an ag-lime surface like our current infield and are constructed with old railroad ties. This is an area that we feel needs improvement for both the home team and the visiting team.

Renovated seating areas

- Mid-Prairie is known for our chair seating areas, where you bring a lawn chair along to watch and if you choose there is a set of bleachers for use as well. Due to the issues surrounding the retaining wall blocks currently in place, we are looking to remove all of that blocking and replace those seating areas and hopefully expand upon them to provide additional seating area.

Total estimated costs for these projects are **\$110,000**